


## FITNESS CERTIFICATE

- 1 Name of Officer : Assistant Engineer, LID & EW Section,  
Chempu Grama Panchayathu
- 2 Name of School : LAKE MOUNT PUBLIC SCHOOL
- 3 Location with name of Edn.District/Sub.District : Location – Chempu,  
Edn. Dist - Kaduthuruthy, Sub Dist - Vaikom
- 4 Period for which certificate issued : 2025-26
- 5 Classification of building :
- Permanent building : 55.90 x 12.50 x 3.50m (15 Class Rooms)
- : 5.75 x 3.55 x 3.50m (1 Library & 3 Labs)
- 6 Nature of Defect : Nil
- a) Foundation and basement :
- b) Superstructure :
- c) Doors and Windows :
- d) Flooring :
- e) Misc :
- 7 Any major defects noticed which will  
render the building be unsafe in any  
Manner : No
- 8 Whether maintenance works have been  
done properly : Yes
- 9 Remarks : Certified that the school building was  
inspected by me on 30/05/2025 and found  
that the rooms stated above are safe as on  
this date and is sound for conducting classes  
strictly only under normal weather condition.

Place: Chempu

Date:30/05/2025



*Parade*

*SM*

30/05/2025  
SALIN.P.S  
PEN:656416

Assistant Engineer  
LID & EW Section, Chempu.C  
Brahmamangalam P.O