TO BE FILLED BY THE INSPECTING OFFICER (Junior Engineer)

7	Name Officer : Greetha Subshan
2.	Name School : Lake Mount Public School
7.	Location with Edn. Dis.1 Sub Dist Kade the guther Van Com
* 1	Classification of building and size (basis for classification see Annexure 1) Kaduthursuthy, Varkorn Permanent (Multi-Storied)
	(basis for classification see Annexure 1)
	Permanent (Single or multi
	Storyed) Storyed
	Permanent (Single or multi 55.90 m x 12.50 m x 3.5 buylding Storyed) Semi permanent having 15 class 800 ms of Sizie 5.85 m Temporary Shed 5.75 m x 3.55 m x 3.55 m, 1 Library 4 2 labs
	Temporary Shed 5.75 mx 3.55 m x 3.55 m, 1L, 1010
5.	remod for which the certificate is issued
6.	Nature of defects, if any 2019 - 20
	a. Foundation and basement
	b. Superstructure
	d. Woods work wrought and put up
	work wrong it and par up
	e.Roof
	f.Flooring
	g.Misc(Cracks etc.)
	Any Major defects noticed which will
	reader the bulding unsafe in any manner
	Whether maintence works have been
	done properly.
	Whether the structure is sound or not for Sound enough to conduct classes conducting classes under normal weather conditions
	conducting classes under normal weather conditions
	Note:1 The stability of the structure should be examined also with reference to location,
	attitude intensity of wind exposure flood etc,
	2. Any additional observations if deemed necessary /for the certificate my be
	furnieshed separately with the certificate
	cate that the Schoold was inspected by me on 24/09/2020 and
found	to be in Funfit to conduct for the period $2020-21$
	An and the second secon
Place	Brahmam angalam Signature 24/9/2020 Designation
- Charles	24/9/20 20 Designation
	24 19/20 20 Designation
	Seland To Seland
	ALS: mou G.
	Designation Designation Designation Assistant Engineer Chempire B. R. Valvorn Chempire B. R. Valvorn