

TO BE FILLED BY THE INSPECTING OFFICER
(Junior Engineer)

1. Name Officer : *Geetha Subban*
2. Name School : *Lake Mount Public School*
3. Location with Edn. Dis.1 Sub Dist : *Kaduthuruthy, Vaikom*
4. Classification of building and size
(basis for classification see Annexure 1) : *Permanent (Multi-storied)*
 - i. Permanent(Single or multi Storyed) : *55.90m x 12.50m x 3.5 building*
 - ii. Semi permanent : *having 15 classrooms of size 5.85m*
 - iii. Temporary Shed : *5.75m x 3.55m x 3.5m, 1 Library & 3 Labs*
5. Period for which the certificate is issued : *2019-20*
6. Nature of defects ,if any
 - a. Foundation and basement
 - b. Superstructure
 - c. Doors and windows
 - d. Woods work wrought and put up
 - e. Roof
 - f. Flooring
 - g. Misc(Cracks etc.)

} *Nil*

No

Yes

Sound enough to conduct classes under normal weather conditions

Note:1 The stability of the structure should be examined also with reference to location, attitude intensity of wind exposure flood etc,

2. Any additional observations if deemed necessary /for the certificate my be furnished separately with the certificate


Certificate that the Schoold was inspected by me on *24/09/2020* and found to be fit /unfit to conduct for the period *2020-21*

Place *Brahmamangalam*

Signature

Date *24/9/2020*

Designation



LS
Assistant Engineer
L.S.G.D. Section
Chempu G.P., Vaikom